



Solution 5e[®], Premium 5e[®]

Tester Model(s)	Permanent Link Adapter(s)	Channel Adapter(s)
LanTEK II	0012-00-0629 ¹ 0012-00-0656 ²	0012-00-0629 ¹ 0012-00-0656 ²
LanTEK III-500MHz LanTEK III-1000MHz	R161051	R161053

Note(s):

¹ Category 6/Class E Universal Channel/Permanent Link Adapter

² Category 6A/Class E_A Universal Channel/Permanent Link Adapter





Solution 6°, System 6°, Premium 6°, Z-MAX™ Premium 6°

Tester Model(s)	Permanent Link Adapter(s)	Channel Adapter(s)
LanTEK II	0012-00-0629 ¹ 0012-00-0656 ²	0012-00-0629 ¹ 0012-00-0656 ²
LanTEK III-500MHz LanTEK III-1000MHz	R161051	R161053

Note(s):

NA = Not available/approved at this time

¹ Category 6/Class E Universal Channel/Permanent Link Adapter

² Category 6A/Class E_A Universal Channel/Permanent Link Adapter





Z-MAX™ 6A

Tester Model(s)	Permanent Link Adapter(s)	Channel Adapter(s)
LanTEK III-500MHz LanTEK III-1000MHz	R161051	R161053

Note(s):





TERA® 600MHz, TERA® 1000MHz

Tester Model(s)	Permanent Link Adapter(s)	Channel Adapter(s)
LanTEK III-1000MHz	R161054 ¹	R161054

Note(s):

¹ IDEAL specifies the use of their Universal TERA adapter for both Permanent Link and Channel testing. Permanent Link testing is to be performed with a TERA-to-TERA patch cord.





Revision Log

- **August 17, 2018:** Siemon has approved the use of the IDEAL LanTEK III tester for testing of category 5e, 6, 6A, 7 and 7A system warranties. Tester firmware versions have been removed from tracking – latest versions should be used unless otherwise noted.
- **May 27, 2015:** Siemon only supports the use of the LanTEK II field tester for testing all category 5e and category 6 system warranties. All other field testers are no longer approved
- **March 11, 2013:** New software version 2.019 required for LanTEK II unit.
- **November 11, 2011:** Siemon Company has approved the LanTEK II field tester for testing of all Category 5e and Category 6 System Warranties.
- **July 26, 2006:** Added reference to newer (LanTEK 6A and 7G) models. New software version 2.508 required for all LanTEK units. Updated p/n for optional Siemon patch cord.
- **May 30, 2007:** New software version 2.600 required for LT 8100, 8155 and 8600 units.
- **May 30, 2007:** New software version 2.510 required for all LanTEK units.
- **May 30, 2007:** Added Premium 6[®] to system options.

